Telecoms / Voice and Data

MORGAN
SINDALL
CONSTRUCTION

To facilitate this ambition of getting the quality
right, these checks should take place:

➢ Ensure adequate separation from all other cables and heat sources

➢ Ensure sufficient capacity in containment for future modifications / additions?

➢ Ensure cables runs do not exceed 90m

➢ Ensure cable testing result printouts available

➢ If fire suppression is provided to Comms Rooms the room will need to be airtight and pressure tested and pressure relief valves required

➢ Ensure building is sufficiently dry, clean and at the correct temperature for installation of data cables

➢ Protect all cables within floor voids during construction period. (damaged cables cannot be repaired - they must be replaced)

➢ Check that any air conditioning has been operating for a sufficient proving period prior to commissioning of comms room equipment and systems

➢ Coordinate water services to avoid running over comms rooms

Our Quality vision:

We will get it right first time on all our projects
by delivering exceptional customer service

Get it right!